

Pump Outlet Filter Repair Kit

InvisiPac® Tank-Free™
Hot Melt Delivery Systems

407123C

EN








Important Safety Instructions

Read all warnings and instructions in the InvisiPac system manual.

NOTICE

Shoulder bolt (6) is left-hand threaded. To prevent damage to the threads, turn clockwise to remove and counterclockwise to tighten.



- 24T179  Apply anti-seize to threads.
- 24T156  Apply lubricant surfaces shown.
-  Torque to 70+/- in-lbs. (7.9 N•m).
-  Shoulder bolt (6) is left-hand threaded.

GRACO INC. AND SUBSIDIARIES • P.O. BOX 1441 • MINNEAPOLIS MN 55440-1441 • USA
Copyright 2014, Graco Inc. All Graco manufacturing locations are registered to ISO 9001.

407123, Revision C, March 2017