

2150 Manifold Seal Repair Kits

3A7560B

EN

NOTE: Ensure the correct parts are provided with your kit. Refer to the kit identifier on your kit package and compare to the table below.

Kit Identifier	For use with Pump Family	Pump Repair Manual*	Kit Includes
H1	Husky™ 2150 (Plastic), AODD	308550	4 o-rings
	Husky 2150 (Metal), AODD	308368	4 o-rings
	Husky 2150, EODD	3A5131	4 o-rings
	QUANTM™ QTE	3A8946	4 o-rings
H2	SaniForce® 2150 FG, AODD	311879	4 o-rings
	SaniForce 2150 FG, EODD	3A5133	4 o-rings
	QUANTM QHE-FG	3A9287	4 o-rings
H3	SaniForce 2.0 2150, AODD	3A6782	4 sanitary gaskets
	SaniForce 2.0 2150, EODD	3A5133	4 sanitary gaskets
	QUANTM QHE-HS, PH, 3A	3A9287	4 sanitary gaskets

*See the pump Repair manual for instructions and optional available materials.

Customer Service and Technical Support

North America and South Central America

866-348-3188

Europe, Middle East, and Africa

UK/Scandinavia: +32 89 770 847

France: +32 89 770 747

Italy: +32 89 770 844

Netherlands (Dutch): +32 89 770 845

Spain: +32 89 770 849

Germany/Austria/CH: +32 89 770 848

Russia: +32 89 770 846

Asia Pacific

86-21-64950088

California Proposition 65

CALIFORNIA RESIDENTS



WARNING: Cancer and reproductive harm – www.P65warnings.ca.gov.

PROVEN QUALITY. LEADING TECHNOLOGY.

All written and visual data contained in this document reflects the latest product information available at the time of publication. Graco reserves the right to make changes at any time without notice.

Original instructions. This manual contains English. MM 3A7560

Graco Headquarters: Minneapolis

International Offices: Belgium, China, Japan, Korea

GRACO INC. AND SUBSIDIARIES • P.O. BOX 1441 • MINNEAPOLIS MN 55440-1441 • USA
Copyright 2020, Graco Inc. All Graco manufacturing locations are registered to ISO 9001.