3150 and 3250 Manifold Seal Repair Kits



FN

NOTE: Ensure the correct parts are provided with your kit. Refer to the kit identifier on your kit package and compare to the table below.

Kit Identifier	For use with Pump Family	Pump Repair Manual*	Kit Includes
K0	SaniForce® 1.0 3150 HS and 3A series	310622	12 sanitary gaskets
K1	SaniForce 2.0 3150, AODD	3A6782	4 sanitary gaskets
	SaniForce 2.0 3000, EODD	3A5133	4 sanitary gaskets
	SaniForce 2.0 3250, AODD	3A6783	4 sanitary gaskets
	QUANTM™ QHF	3A9287	4 sanitary gaskets

^{*}See the pump Repair manual for instructions and optional available materials.

Customer Service and Technical Support

North America and South Central America

866-348-3188

Europe, Middle East, and Africa

UK/Scandinavia: +32 89 770 847

France: +32 89 770 747 Italy: +32 89 770 844

Nederlands (Dutch): +32 89 770 845

Spain: +32 89 770 849

Germany/Austria/CH: +32 89 770 848

Russia: +32 89 770 846

Asia Pacific

86-21-64950088

California Proposition 65

CALIFORNIA RESIDENTS

MARNING: Cancer and reproductive harm – www.P65warnings.ca.gov.

PROVEN QUALITY. LEADING TECHNOLOGY.

All written and visual data contained in this document reflects the latest product information available at the time of publication.

Graco reserves the right to make changes at any time without notice.

Original instructions. This manual contains English. MM 3A7562

Graco Headquarters: Minneapolis International Offices: Belgium, China, Japan, Korea

GRACO INC. AND SUBSIDIARIES • P.O. BOX 1441 • MINNEAPOLIS MN 55440-1441 • USA Copyright 2020, Graco Inc. All Graco manufacturing locations are registered to ISO 9001.